

## SERVICE BULLETIN WASHING MACHINE

**MODEL:** ESV80HA


**SUBJECT:** Replacing the door lock.

**GENERAL:** Incompatibility issue may occur if incorrect door lock was ordered for different production lots. Please refer to the below on how to identify different version and order appropriate part.

**PARTS**

**ACTION:** If you are servicing above model, please order appropriate door lock type per below chart:

ITEM	Description	Part Code			
		OLD	SUBSTITUTE	Qty	Price code
10	Door lock (A)	V-32024465	V-32024464	1	AP
10	Door lock (B)		V-10651989	1	AP



**PRODUCTION**

**CHANGE:** From 1<sup>st</sup> lot.